

# Oil Field Environmental Incident Summary

**Incident:** 20131213175025      **Date/Time of Notice:** 12/13/2013 17:44  
**Responsible Party:** Burlington Resources  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** MATHISTAD 2-35H  
**Field Name:** CROFF      **Well File #:** 18013  
**Date Incident:** 12/13/2013      **Time Incident:** 13:00      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 96      **Sec:** 35      **Qtr:** SE SW  
**Location Description:** Immediately adjacent to the North east side of the well pad

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Miles  
**Distance Nearest Water Well:** 1 Miles

**Type of Incident:** Other

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Reported to NRC:</b> No	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	<b>10</b>	<b>gallons</b>	0	barrels			
<b>Brine</b>	0	barrels	0	barrels			
<b>Other</b>	0	barrels	0	barrels			

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 8/3/2016      **Clean Up Concluded:** 12/30/2013  
**Risk Evaluation:**

**Areal Extent:**  
approximately 20 feet by 100 feet

**Potential Environmental Impacts:**

**Action Taken or Planned:**

The oil impacted snow and ice will be brought back onto the pad and placed into one of the tanks for oil recovery. Oil impacted soil and debris will be collected and sent for appropriate disposal.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 12/16/2013 **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Spray of oil off location. Followup is necessary.

---

**Date:** 12/17/2013 **Status:** Inspection

**Author:** Clary, Shane

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Shane Clary arrived on location on 12/17/13. After arrival, it was clear that no cleanup had taken place yet. An area of snow approximately 50x20 yards to the SE of the pad was stained with oil. I placed a call to the company contact who verified that clean-up crews have not arrived to the spill yet. The contact stated that the spill would be cleaned up in the days to follow. A follow-up inspection is required to verify that proper clean-up actions have taken place.

---

**Date:** 12/31/2013 **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

14:03, on location. No visible stain on/underneath snow to NW/N/NE of treater and tanks in stubble field. Previous inspection indicated spill was at SE corner of site, not NE corner; however, no visible stain on snow in SE area of pad.

---

**Date:** 11/6/2014 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Site closed; no additional followup is necessary.